


Diagramma perdite di carico

Load loss diagram


VALVOLE A SFERA A DUE VIE - PASSAGGIO TOTALE / TWO-WAY BALL VALVES - FULL BORE

Ø	KV
1/4"	14
3/8"	16
1/2"	30
3/4"	50
1"	70
1 1/4"	110
1 1/2"	200
2"	300
2 1/2"	450
3"	570
4"	870




VALVOLE A SFERA A DUE VIE - PASSAGGIO RIDOTTO / TWO-WAY BALL VALVES - REDUCED BORE

Ø	KV
3/8"	8
1/2"	10,5
3/4"	15,5
1"	36
1 1/4"	70
1 1/2"	88
2"	150



VALVOLE A SFERA A TRE VIE - PASSAGGIO TOTALE / THREE-WAY BALL VALVES - FULL BORE

Ø	KV
1/4"	2,55
3/8"	2,75
1/2"	3,67
3/4"	10,19
1"	12,74
1 1/4"	19,65
1 1/2"	33,14
2"	51,07



VALVOLE A SFERA A TRE VIE - PASSAGGIO RIDOTTO / THREE-WAY BALL VALVES - REDUCED BORE

Ø	KV
1/4"	2,66
3/8"	2,88
1/2"	2,27
3/4"	5,5
1"	10,76
1 1/4"	17,26
1 1/2"	24,97
2"	45,09

